

EAST - [Untitled1:2]

File View Edit Tools Window Help

Pending

Active

L2: (11) 11 and ATV

L1: (707) ((296/102) or (296/77.1) or (296/79)).CCLS.

L3: (220) ((296/159) or (135/88.05) or (135/88.13) or (235/88.15)).C

Failed

Saved

(537) ((296/65.03-65.08) or (296/65.11-65.12)).CCLS.

(1) ("4090579").PN.

(23) (296/65.12).CCLS.

(424) (414/921).CCLS.

(26) ("RE19078" | "2290464" | "2587679" | "2822858" | "3865427" | "4

(0) 6582181.URPN.

(16) ("2290464" | "2587679" | "2822858" | "4483653" | "4733903" | "4

(0) 6572172.URPN.

(16) ("2290464" | "2587679" | "2822858" | "4483653" | "4733903" | "4

(1) 6557919.URPN.

Search List Browse Queue

DBs USPAT

☒ Highlight all hit terms initially

296/159

135/88.05

135/88.13

235/88.15

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (30)

UDC

Queue

Trash

	U	I	Document ID	Issue Dat	Page	Title	Current
14	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4241893 A	19801230	11	Adjustable seat assembly	248/425
15	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4155587 A	19790522	11	Movable automobile seat	296/65.
16	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2587679 A	19520304	5	Adjustable seat for automobiles	296/68
17	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2290464 A	19420721	4	Adjustable seat mounting for vehicles	296/65.
18	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4306634 A	19811222	6	Lift assembly	414/663
19	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5636884 A	19970610	5	Pivotal seat and support	296/65.
20	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6543848 B1	20030408	105	Vehicular turning seat	297/344
21	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6457765 B1	20021001	12	Vehicle seat arrangement	296/64
22	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6315352 B1	20011113	10	Construction for automobiles that relate	296/202
23	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2839312 A	19580617	4	Combined seating and steering arrangement fo	280/775
24	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6565139 B2	20030520	8	Vehicle canopy	296/77.
25	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6543830 B1	20030408	13	ATV cab assembly	296/77.
26	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6402220 B2	20020611	7	Portable enclosure	296/77.
27	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4950017 A	19900821	11	Kit which provides a removable top assembly	296/77.
28	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6263894 B1	20010724	15	Insect net assembly	135/96
29	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4657299 A	19870414	11	Pickup truck tent pole anchor, operational com	296/159
30	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4652040 A	19870324	8	Pickup truck tent arrangement with tailga	296/159

Ready

CAP NUM

Best Available Copy

EAST - [Untitled1:2]

FileViewEditToolsWindowHelp

Pending

Active

L2: (11) 11 and ATV

L1: (707) ((296/102) or (296/77.1) or (296/79)).CCLS.

L3: (220) ((296/159) or (135/88.05) or (135/88.13) or (235/88.15)).C

Failed

Saved

(537) ((296/65.03-65.08) or (296/65.11-65.12)).CCLS.

(1) ("4090579").PN.

(23) (296/65.12).CCLS.

(424) (414/921).CCLS.

(26) ("RE19078" | "2290464" | "2587679" | "2822858" | "3865427" | "4

(0) 6582181.URPN.

(16) ("2290464" | "2587679" | "2822858" | "4483653" | "4733903" | "4

(0) 6572172.URPN.

(16) ("2290464" | "2587679" | "2822858" | "4483653" | "4733903" | "4

(1) 6557919.URPN.

SearchListBrowseQueue

DBsUSPAT

☒ Highlight all hit terms initially

296/159

135/88.05

135/88.13

235/88.15

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (30)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error I
1	BRS	L2	11	11 and ATV	USPA T	2004/07/2 7 12:27		
2	IS&R	L1	707	((296/102) or (296/77.1) or (296/79	USPA T	2004/07/2 7 13:02		
3	IS&R	L3	220	((296/159) or (135/88.05) or (135/8	USPA T	2004/07/2 7 13:03		

Hits

Details

HTML

ReadyCAP|NUM|

Best Available Copy